## UNITED STATES DEPARTMENT OF COMMERCE Patent and Trademark Office ASSISTANT SECRETARY OF COMMERCE AND COMMISSIONER OF PATENTS AND TRADEMARKS P.O. Box 1450

February 3, 2007

KATHRYN A MARRA General Motors Corporation Legal Staff, Mail Code 482-C23-B21 P.O. Box 300 Detroit MI 48265-3000

Patent No.

: 7,007,649 B2

Alexandria, VA 22313-1450

Inventor(s)

: Madhusudan Raghavan, et al.

Issued

: March 7, 2006

For

**ENGINE VALVE ACTUATOR** 

**ASSEMBLY** 

Doc. No.

GP-304292

To Whom It May Concern:

The Certificate of Correction issued on \_\_\_\_\_\_ January 30, 2007, issued in error, in that error(s) was made in identifying the patent number and/or keying text/corrections, i.e.:

The issue date in the heading of cofe has been incorrectly entered in the heading of the issued cofe. A superseding cofe will be issued to correct the patent issue date to read --March 7, 2006--.

Therefore, a certificate of correction will be issued to correct (supersede) the Certificate of Correction containing error(s), made during preparation of the Certificate of Correction, as noted above.

No further response is required, from applicants (attorney). However, errors discovered by attorney, other than as noted and described above, should be noted on *a copy* of the Certificate of Correction that was issued in error, accompanied by a signed transmittal letter and submitted directed to this Branch.

Antonio Johnson (703) 308-9390 ext. 111 For Cecelia Newman, Supervisor Decisions & Certificates of Correction Branch (703) 305-8309 / 703-308-9390 ext. 102 cbn